



Infection Prevention Solution
Visitor Thermal Screening System

Infection-Config

Version	Update Information
1.0.2.1635	1. Supported FRS V2 function.
1.0.2.1633	1. Fixed the time stamp of temperature event is wrong on the 1st of every month. 2. Add Traditional Chinese language
1.0.2.1632	1. Support face recognition via FCS. 2. Add a new alarm rule of 'NG Photo' 3. Increase the number of alarm up to 10 4. Auto disable 'Windows Fast Startup'function
1.0.2.1630	1. Update the thermal camera's SDK, in order to fix the bug that the time stamp of temperature event is wrong on the 1st of every month.
1.0.2.1629	1. Can also generate the temperature event, even though the VFR is abnormal. 2. Can feedback the error info when VFR is abnormal.
1.0.2.1627	1. When the "HIKthermalUtil" doesn't connect with "VFR" successfully, it will retry again every 15 seconds. 2. Increase the maximum number from five to seven.
1.0.2.1626	1. Fix thermalUtil code to UTF-8
1.0.2.1624	1. Optimization Alarm policy to avoid same person has lots alarm type 2. Setup priority fot alarm, stranger type setup to low 3. Add device flag, temperture device or social distancing device
1.0.2.1618	1. add no mask in alarm type 2. No stranger output when connecting failed
1.0.2.1613	1. add 2 description message 2. won't be overwirte LPSConsole.xml when update the software